XBT L1000 4.51 Software Release Notes

06/2007

Minimum System Requirements

PC Pentium II 350 MHz.

Minimum 4x CD-ROM drive.

Microsoft Windows 98 / 2000 or XP

64 MB. RAM (128 MB. RAM recommended
for Windows 2000/XP.)

30 MB. Free hard disk space.

SVGA video or higher.

Mouse or compatible pointer system.

Installation

Notes
• The XBT L1001M V4.51 CD-ROM provides a simplified version of the software developed for compact and alphanumeric terminals. This CD-ROM also contains all Schneider and Third Party 32 bit protocols.
• The XBT L1003M V4.51 CD-ROM provides a complete version of the software. This CD-ROM also contains all Schneider and Third Party 32 bit protocols.
• The XBT LUP1004 V4.51 CD-ROM provides an update version. The CD-ROM also contains all Schneider and Third Party 32 bit protocols.

To install the software:

Step	Action
1	Insert the XBT L1000 CD-ROM in your CD-ROM drive and follow the instructions on the screen.
2	If the "setup" program does not start automatically: • Select RUN from the START button, • Type D:\SETUP.EXE followed by ENTER (where D: is your CD-ROM drive).

Schneider Electric

Starting XBT L1000

Open the folder in which you have installed the XBT L1000 software.
Double click on the XBT L1000 V4.51 icon.
(Note that an icon has also been placed on your desktop).

<table>
<tr><td colspan="1">

Notes

- The XBT L1001M V4.51 CD-ROM contains the following documents :
  - User guides for Alphanumeric/Matrix terminals and Compact Display Screens.
  - Instruction sheet for Schneider protocols.
  - This release note
  - Instruction sheet for Third Party Protocols

- The XBT L1003M CD-ROM contains, in addition to the above mentioned guides:
  - User guide for Graphic terminals,
  - User guide for the diagnostic option XBT L1003+.

- The XBT LUP1004 V4.51 CD-ROM contains all documents mentioned above.

All documents are provided in English, French, German, Spanish and Italian in PDF format.
</td></tr>
</table>

V4.51 Latest Version

Version V4.51 is the latest version of XBTL1000 software (XBTL1001M - XBTL1003M - XBTLUP1004). It resolves all remaining technical issues and provides a better quality version of XBTL1000.

Installation of XBTLUP1004 V4.51 Update

The installation of the update XBTLUP1004 V4.51 does not require you to have XBTL1003 already installed on your PC.